



THE COUNTRY CLUB
JOHANNESBURG



Lily Pond Maintenance – Woodmead Hole 5

As part of our ongoing efforts to improve the course, we have started focused maintenance on the Lily Pond next to Hole 5 at Woodmead. This feature is central to the visual and strategic identity of Stroke 1, and we are eager to see it revitalised.

The work involves removing invasive reeds and excess vegetation that have accumulated over time. This will enhance both the ecological health of the dam and the visual appeal of the hole.

To carry out this work safely, the pond is currently being drained, with reed removal, general clean-up, and repairs to the surrounding wall to follow.

To minimise disruption to play, the Yellow, White, and Blue tees have been moved forward during this period. You may also notice a strong odour while the dam is drained, thank you for your understanding.

We thank you for your understanding during this short-term disruption and look forward to presenting a cleaner, more refined course feature in due course.

Thank you,
Golf Management



Contact the Golf Department for more information
011 202 1661/2